

PRICE LIST AND OPTIONS



SERVICE/REPAIR Camera Price List

| SERVICE ITEM | PRICE (INCL. VAT) |
|--|------------------------|
| CLA (Clean, Lubricate, Adjust) | £260.00 |
| Rangefinder Calibration ONLY | £95.00 |
| Shutter Speed Calibration ONLY | £95.00 |
| Shutter Curtain Repair - Section Replacement | |
| Polyester | £65.00 |
| Silk | £85.00 |
| Shutter Curtain Repair - Full Replacement | |
| Polyester | £115.00 |
| Silk | £140.00 |
| Beamsplitter Replacement | |
| Screw Mount | £70.00 |
| M Mount | £245.00 |
| Multi-Coated Anti-Reflective Windows | |
| Screw Mount | £95.00 |
| M2/M3/M4 | £95.00 |
| M5/M6/M6TTL/M7/MP/MA | £115.00 |
| Reskin | £70.00 |
| Engraving Retouching or Change | £30.00 |
| Replacement Parts | Dependent on part type |

SERVICE/REPAIR

Lens Price List

| SERVICE ITEM | PRICE (INCL. VAT) |
|---|-------------------|
| CLA (Clean, Lubricate, Adjust) / Screw-Mount | £155.00 |
| CLA (Clean, Lubricate, Adjust) / M-Mount PRE-ASPH | £165.00 |
| CLA (Clean, Lubricate, Adjust) / M-Mount ASPH | £175.00 |
| Fungus Removal | £25.00 |

CONDITION/CUSTOMISE

Camera Price List

| SERVICE ITEM | PRICE (INCL. VAT) |
|---|---|
| Top & Bottom Plate ONLY | |
| (includes engraving painting) | £475.00 |
| Top Plate, Bottom Plate, Back Door, Multiple Fittings | |
| (includes engraving painting) | £535.00 |
| Reskin during Repaint | £50.00 |
| Multi-Coated Anti-Reflective Windows | |
| Screw Mount | £95.00 |
| M2/M3/M4 | £95.00 |
| M5/M6/M6TTL/M7/MP/MA | £115.00 |
| Zinc Pest Reconditioning | Dependent on severity (mild, moderate, acute) |

CONDITION/CUSTOMISE

Lens Price List

| SERVICE ITEM | PRICE (INCL. VAT) |
|---|-------------------|
| Screw Mount (includes engraving painting) | £325.00 |
| M Mount (includes engraving painting) | £365.00 |
| Lens Cap | £65.00 each |
| Lens Hood | £65.00 each |
| 6-Bit Coding (M Mount) | £140.00 |